



- bimetal thermometer
- case Stainless Steel nominal size 63, 80 and 100 mm
- center back
- bulb material Stainless Steel
- accuracy class 1
- DN 63 1/4" - DN 80 1/2" - DN 100 1/2" Stainless Steel process connection
- stem length under thread from 50 to 200 mm
- measuring rangers and lengths can be solved by our workshop

Model TP

Range	Unit	diameter case 63 mm	diameter case 80 mm	diameter case 100 mm
-50 ... +50	°C	TP-63-50/+50-G1/4"-L100-D6X	TP-80-50/+50-G1/2"-L100-D6X	TP-100-50/+50-G1/2"-L100-D6X
-40 ... +40	°C	TP-63-40/+40-G1/4"-L100-D6X	TP-80-40/+40-G1/2"-L100-D6X	TP-100-40/+40-G1/2"-L100-D6X
-40 ... +60	°C	TP-63-40/+60-G1/4"-L100-D6X	TP-80-40/+60-G1/2"-L100-D6X	TP-100-40/+60-G1/2"-L100-D6X
-40 ... +50	°C	TP-63-40/+50-G1/4"-L100-D6X	TP-80-40/+50-G1/2"-L100-D6X	TP-100-40/+50-G1/2"-L100-D6X
-30 ... +70	°C	TP-63-30/+70-G1/4"-L100-D6X	TP-80-30/+70-G1/2"-L100-D6X	TP-100-30/+70-G1/2"-L100-D6X
-20 ... +40	°C	TP-63-20/+40-G1/4"-L100-D6X	TP-80-20/+40-G1/2"-L100-D6X	TP-100-20/+40-G1/2"-L100-D6X
-20 ... +60	°C	TP-63-20/+60-G1/4"-L100-D6X	TP-80-20/+60-G1/2"-L100-D6X	TP-100-20/+60-G1/2"-L100-D6X
-20 ... +80	°C	TP-63-20/+80-G1/4"-L100-D6X	TP-80-20/+80-G1/2"-L100-D6X	TP-100-20/+80-G1/2"-L100-D6X
0 ... +60	°C	TP-63-0/+60-G1/4"-L100-D6X	TP-80-0/+60-G1/2"-L100-D6X	TP-100-0/+60-G1/2"-L100-D6X
0 ... +80	°C	TP-63-0/+80-G1/4"-L100-D6X	TP-80-0/+80-G1/2"-L100-D6X	TP-100-0/+80-G1/2"-L100-D6X
0 ... +100	°C	TP-63-0/+100-G1/4"-L100-D6X	TP-80-0/+100-G1/2"-L100-D6X	TP-100-0/+100-G1/2"-L100-D6X
0 ... +120	°C	TP-63-0/+120-G1/4"-L100-D6X	TP-80-0/+120-G1/2"-L100-D6X	TP-100-0/+120-G1/2"-L100-D6X
0 ... +160	°C	TP-63-0/+160-G1/4"-L100-D6X	TP-80-0/+160-G1/2"-L100-D6X	TP-100-0/+160-G1/2"-L100-D6X
0 ... +200	°C	TP-63-0/+200-G1/4"-L100-D6X	TP-80-0/+200-G1/2"-L100-D6X	TP-100-0/+200-G1/2"-L100-D6X
0 ... +250	°C	TP-63-0/+250-G1/4"-L100-D6X	TP-80-0/+250-G1/2"-L100-D6X	TP-100-0/+250-G1/2"-L100-D6X
0 ... +300	°C	TP-63-0/+300-G1/4"-L100-D6X	TP-80-0/+300-G1/2"-L100-D6X	TP-100-0/+300-G1/2"-L100-D6X
0 ... +400	°C	TP-63-0/+400-G1/4"-L100-D6X	TP-80-0/+400-G1/2"-L100-D6X	TP-100-0/+400-G1/2"-L100-D6X
0 ... +500	°C	TP-63-0/+500-G1/4"-L100-D6X	TP-80-0/+500-G1/2"-L100-D6X	TP-100-0/+500-G1/2"-L100-D6X
0 ... +600	°C	TP-63-0/+600-G1/4"-L100-D6X	TP-80-0/+600-G1/2"-L100-D6X	TP-100-0/+600-G1/2"-L100-D6X